
PUBLIC WORKS DEPARTMENT (B & R), HARYANA

20

9/2027



Office of the: Executive Engineer, Provincial Division, PWD B&R Br., Faridabad. Tele – **0129-2288187** Email ID: <u>pwd-eepd1-faridabad@hry.nic.in</u>

To

The Principal, Govt. Boys Sr. Sec. School, Tigaon, Faridabad.

4620

Subject: - Building Structure Safety Certificate of Government Boys Sr. Sec. School at Tigaon, GMSSSS Faridabad.

Dated

Reference:- Your letter No. 348/2020 dated 21.09.2020.

In this connection of above cited subject, it is submitted that the above said school building is inspected by Sub Divisional Engineer, Provincial Sub Division No.2, PWD B&R Br., Faridabad along with concerned Sh. Mahipal Singh Junior Engineer of this office on 28.09.2020. The school building having three blocks as shown in layout plan i.e. A,B,C. The year of construction of Block (A) is approx. 2005-2006 and Block (B) is approx 55-60 year old & the Block (C) was constructed in year 2010. The following are the futures of the school building observed during the inspection of the school building.

BLOCK (A) :-

Ground Floor :-

At ground floor there are 05 no. classrooms, 01 no. Science room, 01 no. Physical Education room, 01 no. DTH room, 01 no. Store room, 01 no. Chowkidar room, 01 no. Toilet block and 01 no. Staircases exist at ground floor.

First Floor:-

At first floor there are 05 no. classrooms, 01 no. Computer room, 01 no. Director room, 01 no. Boys toilet, 01 no. Girls Toilet, 01 no. Toilet block and 01 no. Staircases exist at first floor.

BLOCK (C) :-Ground Floor :-

At ground floor there are 03 no. classrooms, 01 no. Computer Lab, 01 no. Office, 02 no. Toilet blocks and 01 no. Staircases exist at ground floor. The school building Block (A) is frame structure having RCC column, beams, slab & 9" thick load bearing outer walls exist. The block (C) having RCC slab & (" thick load bearing outer walls. The plinth level of block (A) and (C) is higher than in comparision to the block (B). Keeping in view all the circumstances the Govt. school building block (A) & (C) seems to be safe. However periodical inspection must be insured.

DA/Nil

1

£

Executive Engineer, Provincial Division. PWD B&R Br., Faridabad

Endst. No.

Dated:-

Copy of above is forwarded to the Sub Divisional Engineer, Provincial Sub Division No.2, PWD B&R Br., Faridabad for information w.r. to his office memo No. 714 dated 29/09/2020.

DA/ Nil

Executive Engineer, Provincial Division, PWD B&R Br., Faridabad.